

# DTA72



## Motor thermistor relay



### Benefits

- **High operating safety.** The thresholds are determined by the Motor internal PTC. Beyond the specified temperature the output stops the motor/s.
- **Save time and costs.** There is no need to connect other additional and expensive controllers.
- **Ensure continuous production process in your plant.** This type of controller allows limitation of false alarms which may be the cause of useless interruptions of production systems when comparing with other electrical measures (i.e. current or power).
- **Two outputs.** The 2 outputs provide, besides interrupting the motor supply, an additional signal for a lamp, PC or PLC.
- **Bi-colour front LED.** It provides indications about alarm status and alarm discrimination.


### Description

DTA72 is a motor thermistor monitoring relay. Through the motor internal PTC or PTCs the DTA detects when one or more motor windings are exceeding the maximum operating winding temperature. The PTC type installed in the motor is different according to the motor insulation temperature. The temperature triggering threshold is determined by the PTC Type. DTA72 is equipped with 2 outputs which operate in a complementary mode. It can be set to operate as MANUAL or AUTO reset.

### Applications

This product is extremely suitable for pumps temperature monitoring. It can be useful in all applications where motors are used especially where overloads are frequent and may cause motor damages: pumping stations, water treatment, conveyors, material handling, HVAC, chillers. etc.

## Structure




Element	Component	Function
A	Output 1 terminals	SPDT electromechanical relay contacts output. Energised during normal operation, it is de-energised upon alarm
B	Information LED	Green ON steady: no alarm Red ON steady: over-temperature alarm Fast Red blinking: open circuit PTC Slow Red blinking: short-circuit Red and Green alternate: ready for reset
C	TEST / RESET pushbutton	When no overtemperature alarm is present, this double function pushbutton, operates as TEST by simulating the PTC over-temperature: motor stops as long as pushbutton is pressed, as soon as pushbutton is released the normal operation is restored. The pushbutton operates as RESET when the motor had been stopped by overtemperature, the setting is for MANUAL reset and the LED shows the "Ready for reset" situation.
D	Remote RESET pushbutton terminals	To configure the device as Autoreset they shall be jumpered
E	Power Supply terminals	A1 ( + or L ) A2 ( - or N )
F	Output 2 terminals	SPDT electromechanical relay contacts output. De-energised during normal operation, it is energised upon alarm.
G	PTC input	Up to 6 PTCs in series can be connected

## Features

### General

<b>Material</b>	PA66 or Noryl
<b>Assembly</b>	DIN rail mounting (According to EN 50022)
<b>Protection degree</b>	IP20
<b>Weight</b>	150 g
<b>Terminals</b>	Screw terminals. AWG30 to AWG12 (0.06 mm <sup>2</sup> to 3.3 mm <sup>2</sup> ) stranded or solid



### Power supply

<b>Power supply</b>	24 to 240 VAC/DC (18 to 265 VAC/DC), 50 to 60 Hz (45 to 65 Hz) or DC
<b>Consumption</b>	3 VA ( AC supply ) / 1.5W ( DC supply )

### Environmental

<b>Working temperature</b>	-25° C to 60° C (-13° F to 140° F)
<b>Storage temperature</b>	-40° C to 80° C (-40° F to 176° F)
<b>Relative humidity</b>	5-95% non condensing
<b>Pollution degree</b>	2
<b>Operating max altitude</b>	2000 m amsl ( 6560ft )
<b>Salinity</b>	No saline environment
<b>UV resistance</b>	No UV exposure

## Compatibility and conformity

<b>Standard compliance</b>	EN60255-6
<b>Approvals</b>	 (UL508, CSA 22.2)
<b>CE Marking</b>	L.V. Directive EN60947-5-1, EMC Directive EN 60947-8

## Inputs

Measuring ranges	
<b>Resistance measuring</b>	Input from a series of 1 to 6 PTC according to EN44081 or IEC34-11-2
<b>Cable length</b>	Max. 600m (wire 1.5mm <sup>2</sup> ) or 200m (wire 0.5mm <sup>2</sup> )

Alarm detection	
<b>Over-temperature trip</b>	> 3600 $\Omega$
<b>Over-temperature reset</b>	< 1580 $\Omega$
<b>Short-circuit protection</b>	14 $\Omega$ (reset 16 $\Omega$ )
<b>Open circuit detection</b>	20 k $\Omega$ (reset < 18 k $\Omega$ )
<b>Switching frequency</b>	< 1Hz
<b>Refresh time</b>	500 ms

## Outputs

<b>Type</b>	2 x SPDT electromechanical relay
<b>Logic</b>	
<b>Output 1</b>	De-energised on alarm
<b>Output 2</b>	Energised on alarm
<b>Contact rating</b>	NEMA B 300 240 Vac AC1 8 A @ 250 Vac DC12 5 A @ 24 Vdc AC15 2.5 A @ 250 Vac DC13 2.5 A @ 24 Vdc

## Insulation


Basic Insulation	
<b>Inputs to output 1</b>	2.5kVrms, 4kV impulse 1.2/50us
<b>Inputs to output 2</b>	2.5kVrms, 4kV impulse 1.2/50us
<b>Inputs to supply</b>	2.5kVrms, 4kV impulse 1.2/50us
<b>Output 1 to supply</b>	2.5kVrms, 4kV impulse 1.2/50us
<b>Output 2 to supply</b>	2.5kVrms, 4kV impulse 1.2/50us
<b>Output 1 to output 2</b>	2.5kVrms, 4kV impulse 1.2/50us

## Operating diagram


When the temperature of one of the PTCs in series is exceeded, output relays will both switch: relay 1 is de-energised and output relay 2 is energised. The LED is ON red.

When the motor normal temperature is restored, if the DTA04 is wired as "Auto reset", the operation is restarted automatically.

If the DTA04 is wired as manual reset when the normal motor temperature is restored the LED starts blinking alternatively red and green indicating it is ready for reset. When the front or the remote RESET buttons are pressed the operation starts again. The LED turns to green and the output relays switch back to original position.



# Connection Diagrams



Code	Description
<b>K1</b>	Main contactor
<b>START</b>	Machine start pushbutton
<b>STOP</b>	Machine stop pushbutton
<b>RESET</b>	Remote reset button
<b>L1</b>	Green lamp (OK)
<b>L2</b>	Red lamp (Alarm)
<b>❶</b>	For Auto Reset operation r1 and r2 shall be jumpered



## References

▶ Order code

 DTA72DM24



COPYRIGHT ©2016  
Content subject to change. Download the PDF: [www.productselection.net](http://www.productselection.net)